Work Order I Wednesday, October	D 74699 05, 2011 11:35:26 AM										Page 1
Item ID: D344 Revision ID: Item Name: Pin	43-9		Accept				S	Setup	Start Stop		
Start Date: 10/5. Required Date: 10/1. Reference:	/2011 Start Qty: 8.00 4/2011 Req'd Qty: 8.00			Cust Item I Customer:	D:					1 (0.0 (6 1.0)	1118 (B) 1101 168 1
Approvals: Pro	cess Plan: M.L.J	Date: 11 / 0 0	SPC (Y/N):		ate:]	Run	Start Stop		
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr D3443	Revision Nbr Rev C										
100 	Hardinge CNC LATH Memo	E SMALL	0.00				8		Ø	y	All nho
Hardinge CNC Lathe Sma		AS PER FOLIO FA698 & DV	WG D3443 ,□FOLIO □2-DEBURR AS REQ	QUIRED							٠,
	QC2- Inspect parts off	machine FAI/FAIB	0.00				8		þ	F	Alf viliali
QC Quality Control	Memo		0.00								
<i>J</i> 120 ∭	QC8- Inspect parts - s	econd check	0.00	orl ulioli	, 2		8				
QC	Memo		0.00	1110//	J				K.		

Quality Control

Dart Ae	rospace L	.td								
W/O:			WO	RK ORDER CHANG	ES	-				-
DATE	STEP	PR	OCEDURE CHAN	NGE	Ву	,	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	jory:	NCR: Y	es N	o DQA	i:	_ Date: _	
	Res	solution:	Disposition);	_ QA: N/0	Clos	sed:		Date: _	
NCR:		A	WORK ORDE	R NON-CONFORMA	NCE (N	CR)				
5		Description of NC		Corrective Action Section	on B		Verifica	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		gn & ate	Sectio		Chief Eng	QC inspector
									· -	

		Description of NC Section A		Corrective Action Section B	Verification	Approval	Approval	
DATE	STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC inspector
							·	
						,		
					*.			

Work Order ID 74699

Page 2

Item ID:

Wednesday, October 05, 2011 L1:35:26 AM D3443-9

Accept

Setup Start

Revision ID:

Start Date:

Item Name: Pin

Required Date: 10/14/2011

10/5/2011

Start Oty: 8.00 Req'd Otv: 8.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Start

Stop



QC:

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop



Sequence ID/ Work Center ID

130

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location: 054

Memo

0.00

0.00

Tool ID

Tool # Plan Accept Qty Code

Reject Qty _

Run

Reject Number Stamp

Insp.

140

OC

Quality Control

QC21- Final Inspection - Work Order Release

Memo

0.00

0.00

M/10/V 1-10-17

W/O:			W	ORK ORDER CHANG	ES									
DATE	STEP	PRO	OCEDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
						W-T								
Part No	•	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A :	_ Date: _						
		esolution:	Disposition:					QA: N/C Closed: Date:						
NCR:			WORK ORE	ER NON-CONFORMA	NCE (NC	₹)	-							
DATE	STEP	Description of NC		Corrective Action Section E			ation	Approval	Approval					
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign a	k Secti		Chief Eng	QC Inspector					
								·						
ı														
		•												
									·					

1	1	l .	1 1		1	1		1	I					

Picklist Print

Wednesday, October 05, 2011 11:35:33 AM

Work Order ID: 74699

Parent Item: D3

D3443-9

Parent Item Name: Pin



Start Date: 10/5/2011

Required Date: 10/14/2011

Page 1

Start Qty: 8.00

Required Qty: 8.00

Comments:

IPP rev A 05.12.19 new issue ec

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MDELRINR0.500 Delrin Round Bar .50"		Purchased	No			110	f	70.8750	0.0875	0,736842	11/10/	13	
				Location		Loc	Qty	Loc Code					

 Location
 Loc Oty
 Loc Code

 MAT055
 70.875
 \$\infty\$. \$\infty\$.

								I
W/O:			W	ORK ORDER CHANG	GES			
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							1 100 Mg	

Part No		PAR #:	Fault Cat	egory:	NCR: Yes	No DQA :	Date: _	
Resolution:		esolution:	Dispositi	on:	QA: N/C Cld	sed:	Date: _	
NCR:			WORK ORI	DER NON-CONFORM	ANCE (NCR)		
DATE	STEP	Description of NC		tion B	Verification	Approval	Approval	
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
							·	
			·					
					`.			
I	1	I .	1				1	

D3065-5DART AEROSPACE LTD	Work Order:	74699
Description: Pin	Part Number:	D3443-9
Inspection Dwg: D3443 Rev: C		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST


X First Article	Prototype
-----------------	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.210	+0.005/-0.010	0.212	V ,		SLOZ	
1.05	+/-0.030	1.045			SL 08	
						1
				,		
i	ii					


Measured by:	Audited by:	and	Prototype Approval:	N/A
Date: 11/10/13	Date:	11/10/13	Date:	N/A

ſ	Rev	Date	Change	Revised by	Approved
Ì	Α	06.09.01	New Issue	KJ/JLM 1 A	
Ī	В	09.11.04	Dwg Rev updated	KJ 94	M
		·		()	, , ,


W/O:			W	ORK ORDER CHAN	GES					
DATE	STEP	PRO	OCEDURE CH	ANGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	·									
							•			
		PAR #:	PAR #: Fault Category:					\:	Date:	
		esolution:	Dispositi	on:	QA: N	/C Clos	sed:		Date:	
			WORK ORDER NON-CONFOR Corrective Action							
DATE	STEP	Description of NC	Initial	ection B	— veriti			Approval	Approval	
		Section A	Chief Eng	Action Description Chief Eng		Date	Section	on C	Chief Eng	QC Inspector
							,			
										· ·
										
<u></u>		1	,				1		1	




W/O:		•	CW	RK ORDER CHANG	ES				<u> </u>	
DATE	STEP	PR	GE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
	8. 6. 2 1.									
		· · · · · · · · · · · · · · · · · · ·								
		PAR #:	PAR #: Fault Category: NO			No DC	A:	Date:		
		esolution:				QA: N/C Closed:			Date:	
NCR:				R NON-CONFORM	ANCE (NC	R)				
DATE	STEP	Description of NC					cation Approval		Approval	
		Section A	Chief Eng	Action Description Chief Eng	Date		tion C	Chief Eng	QC Inspector	



									t-		
W/O:			W	ORK ORDER CHANG	ES						
DATE	STEP	PF	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
16											
				7. A. Tarana (1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1							
Part No	:	PAR #:	Fault Category: N			NCR: Yes No DQA: Date:					
		esolution:	Dispositi	on:	QA: N/C Closed: Date:						
NCR:			WORK ORE	DER NON-CONFORMA	NCE (NCR)					
DATE	STEP	Description of NC Section A	Corrective Action Section			Verification		Approval	Approval		
DATE	SIEF		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC Inspector		
	:										
							•				



W/O:			wc	RK ORDER CHANG	FS	·	****		
DATE STEP		PROCEDURE CHANGE			Ву	Date	e Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA	\ :	Date:	
		esolution:							
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCF	R)	,		
		Description of NC		ion B	Verification		Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	n& Section C	Chief Eng	QC Inspector	
								·	
									·
			·					,	
									:
					`.				



DESIGN	RF	DART AEROSPACE LTD			
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA			
CHECKED	.00	DRAWING NO. REV. C			
MFG. APPR.	M/V	D3443 SHEET 4 OF 4			
APPROVED	700	TITLE SCALE			
DE APPR.		STRUT WELDMENT ASSEMBLY			
DATE 09.0	06.25	COPYRIGHT © 2005 BY DART AEROSPACE LTD THIS DOCUMENT IS PREVALE AND CONFIDENTIAL AND IS BUPPLED ON THE EXPRESS CONCIDENTIALT IT IS NOT TO BE USED FOR ANY AMPOSES ON COMPANY DATE OF THE TOWN PURSON WITHOUT			

Dart Ae	rospace	Ltd						,
W/O:			WO	RK ORDER CHANGES	3			€ s. *
DATE	STEP	PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
						·		-
Part No		PAR #:				The state of the s		
	R	esolution:	Disposition	n:	QA: N/C C	losed:	Date: _	
NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCF	R)		
DATE	OTED	Description of NC		В	Verification	Approval	i Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto
								·
					, ,			
						•		